

# Your diagnosis of 06.04.25

RENAULT Trafic - FV-606-ZZ - 57.590 km

## Front left



EfficientGrip Cargo

205/65R16 107 T Summer ☀

Produced in May 2020 - Spain

## Diagnosis

- Worn tyre, limited tread height, risk of aquaplaning

## Recommendation

- Replacement recommended

Change my tyres

## Rear left



EfficientGrip Cargo

205/65R16 107 T Summer ☀

Produced in May 2020 - Spain

## Diagnosis

- Good tread depth

## Recommendation

- Next check 6 months or 5,000 kms

Our advices

## Front right



EfficientGrip Cargo

205/65R16 107 T Summer ☀

Produced in May 2020 - Spain

## Diagnosis

- Worn tyre, limited tread height, risk of aquaplaning

## Recommendation

- Replacement recommended

Change my tyres

## Rear right



EfficientGrip Cargo

205/65R16 107 T Summer ☀

Produced in May 2020 - Spain


## Diagnosis

- Good tread depth

## Recommendation

- Next check 6 months or 5,000 kms

Our advices



Checking mounting directions: **OK**

Same brand, pattern, dimension for each axle: **OK**

Presence of a cut, hernia, crack: **OK**

Tyres compliant with mountain law (3PMSF): **No**

**If at least one of your tyres shows some issues, we recommend that you contact a professional and carry out the recommended changes for your peace of mind.**